

ARRIVAL ROUTE DESCRIPTION

KPBI: from CLMNT on track 214° to MAZEL.

LANDING KPBI RUNWAYS 10L, 14: from MAZEL on track 214° to cross FRWAY at 4000, then on track 224° to TUNNE, then on track 224° to cross SANZZ at 4000 and at 210K, then on track 271° to cross DLMAN at 4000, then on track 271°. Expect RADAR vectors to final approach course.

LANDING KPBI RUNWAY 28R: from MAZEL on track 214° to cross FRWAY at 4000, then on track 176° to cross HETMO at 4000 and at 210K, then on track 177° to TROLN, then on track 098° to cross WTCAP at 4000, then on track 098°. Expect RADAR vectors to final approach course.

LANDING KPBI RUNWAY 32: from MAZEL on track 214° to cross FRWAY at 4000, then on track 176° to cross HETMO at 4000 and at 210K, then on track 175° to EHMON, then on track 141° to cross KIDGE at 4000, then on track 141°. Expect RADAR vectors to final approach course.

LANDING 06FA/F45: from CLMNT on track 214° to MAZEL, then on track 214° to cross FRWAY at 4000, then on track 271° to cross AMILA at 4000, then on heading 270° or as assigned by ATC. Expect RADAR vectors to final approach course.

LANDING KBCT: from CLMNT on track 214° to MAZEL, then on track 219° to cross KLUBZ at 5000, then on track 224° to TUNNE, then on track 204° to HUSPU, then on track 183° to JESNA, then on track 209° to cross WHILE, at 5000, then on heading 210° or as assigned by ATC. Expect RADAR vectors to final approach course.

LOST COMMUNICATIONS:

KPBI LANDING RUNWAYS 10L/14: Continue track to DLMAN, then proceed direct GLYPH, then proceed direct WILBA, conduct ILS or RNAV 10L approach.

KPBI LANDING 28R: Continue track to WTCAP, then proceed direct CUPED, conduct ILS or RNAV 28R approach.

KPBI LANDING 32: Continue track to KIDGE, then proceed direct LIDRE, conduct RNAV 32 approach.